

Approved For Release 2002/08/21 : CIA-RDP89B00569R000800120025-7

DATE 0647Z 22 MAR 64

SECRET

1	10
2	11
3	12
4	13
5	14
6	15
7	16
8	17

TO : DIRECTOR

25X1

FROM :

ACTION: OPS 1-7

INFO :

PRIORITY

25X1

IN-69299

25X1

TCR: 0733Z 22 MAR 64

25X1

TO

PRIORITY

INFO

CITE

25X1

25X1

A. S084A

B. B/119 D7/9,330

C. HIA-36/D-19/2°/78 DEGREES

D. 1.90 1.91/1.94 1.94

E. 9L/8402/247-10-5-11-3 9R/247-9-11-3

F. (1) COLD AND MOIST

(2) GOOD

(3) FAIR

(4) FAIR

(5) GOOD

(6) GOOD

(7) OPERATING

G. REMARKS: TAKE RECEIVED AT 20/2140Z MAR IN SEALED, COVERED METAL CONTAINERS. TRACKER RECEIVED FOR S074A IN GOOD CONDITION. PRESSURE MARKS FROM METERING ROLLER GEAR NOTED AGAIN AS IN S014A, S034A, S064A

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

Approved For Release 2002/08/21 : CIA-RDP89B00569R000800120025-7

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

25X1

 S E C R E T

PAGE TWO

AND S074A FIRST 500 FRAMES 9L. INTERMITTENT STATIC ELECTRICITY
THROUGHOUT BOTH 9R AND 9L. MINOR PINHOLES AND ABRASIONS THROUGHOUT
TAKE. SOME CAUSED BY GRIT IN SPRAY NOZZLES IN HTA-3B. SMALL NEGATIVE
DENSITY SPOTS NOTED NEAR FRAME 1640L AS IN S064A. SMALL TEAR AT
TITLING EDGE IN FRAMES 0818R AND 1865L ACROSS THE FRAME CAUSED BY
IMPROPER TRACKING ON TACKY ROLLER CLEANER. MANUFACTURER SPLICES IN
FRAMES 0092R AND 1888L.

END OF MESSAGE

S E C R E T